Technical Service Bulletin

June 16, 2023

Rotel Bluetooth 5.1 aptX[™] HD Module

The latest Apple iOS version (including OS V15.7.2) may cause the APPLE MUSIC app to stop playing audio when manually jumping between tracks in a playlist. The Bluetooth connection is maintained but there is no audio output and no playback information (sample frequency and/or bit rate) displayed. A hard power cycle of the unit remedies this issue.

Earlier versions of iOS do not appear to have the same issue. Other iOS Apps (i.e. iTunes, Spotify, Tidal, etc.) are NOT affected by this use case.

If this is reported, please contact Rotel at *sales@rotelglobal.com* to order a new Bluetooth 5.1 module (Rotel Part Number: **093E-BTM0002-D-1**) with updated firmware V1.04 (or newer) that resolves this iOS compatibility issue.

Note: All new delivered spare parts will be programmed by new firmware V1.04 (or newer) before package and shipment from now on, either of below two methods can help to identify this change.

1. Check and ensure a printed label with text "V1.04" being pasted on plastic package.



2. Or check and ensure the last 5 digits on the pasted BT ADDRESS label are higher than "28780"



Bluetooth module replacement requires removal of the top cover and replacing the Bluetooth module in the socket (no special tools or soldering is required) as shown below.

Affected unit models include: A12MKII, A11 Tribute, A11MKII, A14MKII, RC-1590MKII, RA-1592MKII, RA-1572MKII, RC-1572MKII, RA-6000

Release Type		
Maintenance	Major	Critical

A12MKII

Software Information	
Main Version	V2.03

Serial Number (Change will be effective in units after the serial numbers listed below.)		
Black	273-314-1100	
Silver	773-314-1100	

A11 Tribute

Software Information	
Main Version	V1.20

Serial Number (Change will be effective in units after the serial numbers listed below.)		
Black	263-319-1300	
Silver	763-319-1200	

A14MKII

Software Information	
Main Version	V3.05

Serial Number (Change will be effective in units after the serial numbers listed below.)		
Black	266-311-1100	
Silver	766-311-1100	

RA-1572MKII

Software Information	
Main Version	V3.03

Serial Number (Change will be effective in units after the serial numbers listed below.)		
Black	267-306-1100	
Silver	767-311-1100	

RA-1592MKII

Software Information	
Main Version	V2.03

Serial Number (Change will be effective in units after the serial numbers listed below.)		
Black	269-312-1100	
Silver	769-312-1100	

RC-1572MKII

Software Information	
Main Version	V3.03

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	268-243-1200
Silver	768-308-1100

RC-1590MKII

Software Information	
Main Version	V2.03

Serial Number (Change will be effective in units after the serial numbers listed below.)		
Black	270-313-1100	
Silver	770-313-1100	

RA-6000

Software Information	
Main Version	V1.03

Serial Number (Change will be effective in units after the serial numbers listed below.)		
Black	265-248-1100	
Silver	765-248-1100	

A11MKII

Software Information	
Main Version	V1.01

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	289-316-1100
Silver	789-316-1100

Release Notes

• Part Number of New Bluetooth Module 5.1 is 093E-BTM0002-D-1

• New Bluetooth module 5.1 built Qualcomm IC as below photo.



The Instruction use RA-6000 Bluetooth Dongle Replacement as example:

a. Remove all top cover screws



b. Remove the Bluetooth 5.1 dongle from the socket.



c. Prepare the new Bluetooth dongle (with firmware V1.04 or higher installed)



d. Install the new Bluetooth 5.1 dongle in the socket. Pay CAREFUL attention to pin alignment to avoid damage to the dongle and the unit.



- e. Reassembly the unit and top cover.
- f. Test to verify the new Bluetooth module works properly.

For more information or questions please contact your customer service representative.

- - End - -