

MICHI

Technical Service Bulletin

December 19, 2023

Michi P5 Series2 - Version 2.04 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V2.04
Previous Version	V2.03

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	282-344-1050

Release Notes
<ul style="list-style-type: none">• Implemented Gain Adjust function to allow an independent level adjustment for sources.• Implemented "Max Volume" to limit the maximum volume to which the unit can turn.• Updated the minimum value of Power On Max Volume to 20 to improve user experience.• Fixed a bug where pop noise occurred when switched between DoP tracks.• Other minor bug fixes.

For more information or questions please contact your customer service representative.

-- End --

MICHI

Technical Service Bulletin

August 16, 2023

Michi P5 Series2 - Version 2.03 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V2.03
Previous Version	V2.01

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	282-328-1001

Release Notes
<ul style="list-style-type: none">• Implemented Child Lock to allow the user to lock the front panel to prevent changing the source input and volume level.• Improved in-house testing processes.• Other minor bug fixes.

For more information or questions please contact your customer service representative.

-- End --

MICHI

Technical Service Bulletin

April 19, 2023

Michi P5 S2 - Version 2.01 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V2.01
Previous Version	V2.00

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	282-301-1050

Release Notes
<ul style="list-style-type: none">• Fixed a bug where relay clicks occurred when the user pressed VOL- remote button with 0 master volume level.• Fixed a bug where the sample rate of digital outputs was not consistent with the PC-USB input.• Improved Network function to eliminate “No Network” problem during online software update.• Other minor bug fixes.

For more information or questions please contact your customer service representative.

-- End --