

Technical Service Bulletin

March 30, 2021

RA-1572 - Version 3.00 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
 Maintenance	Major	Critical

Software Information	
New Version	V3.00
Previous Version	V2.71

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	249-105-1100
Silver	749-105-1100

Release Notes
<ul style="list-style-type: none">• Minor bug fixes and improvements.

For more information or questions please contact your customer service representative.

-- End --



Technical Service Bulletin

June 5, 2019

RA-1572 - Version 2.71 Software Release

The RA-1572 software has been updated to Version 2.71. This release includes several bug fixes and improvements. Release details are listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V2.71
Previous Version	V2.70

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	249-851-1171
Silver	749-912-1100

Release Notes
<ul style="list-style-type: none">Implemented analog signal detection for Off Timer. The feature will be available in hardware versions starting after serial number: Black: 249-851-1171 / Sliver: 749-912-1100.
<ul style="list-style-type: none">Fixed a bug when Off Timer was enabled, the unit fails to enter Standby mode after DSD playback has paused for the designated time.
<ul style="list-style-type: none">Fixed a bug where there is a pause of playback after the Bluetooth Signal Sense power on is activated.
<ul style="list-style-type: none">Fixed a bug where the network stops responding after a period of receiving Speaker A-B commands.

For more information or questions please contact your customer service representative.

-- End --



Technical Service Bulletin

Mar 15, 2019

RA-1572 Version 2.70 Software Release

The RA-1572 software has been updated to Version 2.70. This release includes one improvement. Release details are listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V2.70
Previous Version	V2.69

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	249-851-1171
Silver	749-851-1029

Release Notes
<ul style="list-style-type: none">Reduced the energy consumption of Network Standby mode.

For more information or questions please contact your customer service representative.

-- End --




Technical Service Bulletin

Mar 15, 2019

RA-1572 Version 2.69 Software Release

The RA-1572 software has been updated to Version 2.69. This release includes one improvement. Release details are listed below.

Release Type		
 Maintenance	Major	Critical

Software Information	
New Version	V2.69
Previous Version	V2.68

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	249-842-1200
Silver	749-839-1100

Release Notes
<ul style="list-style-type: none">Improved Bluetooth lost functionality.

For more information or questions please contact your customer service representative.

-- End --

Technical Service Bulletin - #181127

Nov 27, 2018

RA-1572 - Version 2.68 Software Release

The RA-1572 software has been updated to Version 2.68. This release includes one improvement . Release details are listed below.

Release Type

Maintenance	Major	Critical
-------------	-------	----------

Software Information

New Version	V2.68
Previous Version	V2.65

Serial Number (Change will be effective in units after the serial numbers listed below.)

Black	249-823-1100
Silver	749-830-1100

Release Notes

- Improved Auto Off Timer to monitor digital inputs. For example, if we set Auto Off Timer as "20 MINS", then:

If the listening source is Coax, Optical, USB or PC-USB the unit will power off when the source device does not provide an audio signal for 20 minutes.

Note that this improvement requires upgrading RA-1572 and RC-1572 PC-USB software from V1.08 (or older) to V1.11 (or newer). Contact your customer service representative for more information.

For more information or questions please contact your customer service representative.

-- End --

Technical Service Bulletin - #180626

June 26, 2018

RA-1572 - Version 2.65 Software Release

The RA-1572 software has been updated to Version 2.65. This release includes updates for compliance with various power consumption regulations, improved SIGNAL SENSE function as well as other bug fixes and improvements. Release details are listed below.

Release Type

Maintenance	Major	Critical
-------------	-------	----------

Software Information

New Version	V2.65
Previous Version	V2.60

Serial Number (Change will be effective in units after the serial numbers listed below.)

Black	249-823-1100
Silver	749-823-1100

Release Notes

● **NOTICE:** In some regions, POWER OPTION will not be available and the default setting of AUTOMATIC POWER OFF will be 20 MINS due to the limitation of Standby Power Consumption. To control the Rotel product use the RS232 connection.

● Implemented SIGNAL SENSE AUTO. When SIGNAL SENSE was enabled but the last listening source was not the configured source, user puts unit into STANDBY mode and SIGNAL SENSE still could monitor the status of the configured source.
 For example, BLUETOOTH was configured as the SIGNAL SENSE input. The user is listening to PHONO input then she puts the unit into STANDBY mode with remote control. The unit begins to monitor BLUETOOTH input and will wake up and switch to the BLUETOOTH input when a signal is detected.
 If user uses remote control to turn on the unit then the previous input selection is active as in the example the unit would have PHONO as the input.
 If there is audio playing on the configured input when the unit is put into STANDBY the then audio must stop for 10 minutes before SIGNAL SENSE POWER ON is available.

● Added OFF TIMER warning message display. Unit will display a blinking remaining-time message three times in the last three minutes, each for 5 seconds, and will display a static warning message in the last ten second.

● Fixed a bug unit will not save the change of OFF TIMER, PC-USB CLASS and POWER MODE if user change their value without pressing ENTER to confirm the change.

-- Continued --

- | |
|---|
| <ul style="list-style-type: none">• Fixed a bug unit would switch itself on when polled by any control devices via RS232. |
| <ul style="list-style-type: none">• Fixed a bug 12V Trigger stays on after putting unit to sleep in QUICK mode. |
| <ul style="list-style-type: none">• Fixed a bug when SIGNAL SENSE is configured as "BLUETOOTH" and BLUETOOTH stays connected, the status of BLUETOOTH on display would change to "READY" after reboot |

For more information or questions please contact your customer service representative.

-- End --