



# Technical Service Bulletin

November 26, 2020

## RAP-1580MKII - Version 5.03 Software Release

The RAP-1580MKII software has been updated to include bug fixes and improvements as listed below.

**Note:** We suggest disabling Auto Power Down Timer before you perform an Online Upgrade to eliminate the chance that the default 20-minutes Timer could turn off the unit during Software Downloading stage. Note that this issue was fixed in V5.03.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V5.03
Previous Version	V5.00

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	259-036-1140
Silver	759-036-1060

Release Notes
<ul style="list-style-type: none"><li>• Eliminated audio stutter in several occasions.</li><li>• Fixed a bug where Dirac profiles were still displayed in the Filter List on the Dirac Live app after restoring factory default.</li><li>• Fixed a bug where the unit had no output when processing Dolby Atmos content from Netflix.</li><li>• Minor bug fixes related to Dirac function.</li><li>• Minor bug fixes related to the Setup Menu operation.</li><li>• Fixed a bug where unit crashed when booting up with a source that contained HDMI ARC audio input.</li><li>• Updated the text of Online Upgrade process for better clarity.</li><li>• Fixed Dirac bugs that were triggered by the change of Audio System Configuration.</li><li>• Fixed a bug where temporary speaker level adjustment via remote keys "SUB" "CTR" "REAR" did not work properly.</li><li>• Other minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

*-- End --*