

## Technical Service Bulletin

May 23, 2022

### RSP-1576 MKII - Version 3.08 Software Release

The software has been updated to include bug fixes and improvements as listed below.

**Please note that all future upgrades are ONLY available via USB flash drive upgrade. For instruction, please refer to <ROTEL Software Online Upgrading Information> on [www.rotel.com](http://www.rotel.com).**

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V3.08
Previous Version	V3.07

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	258-136-1150
Silver	758-136-1050

Release Notes
<ul style="list-style-type: none"><li>• Fixed a bug with no 4K video output on some models of JVC and Optoma projectors.</li><li>• Fixed a bug where the unit did not save the change when changing OSD resolution from 480p to 576p in the setup menu.</li><li>• Other minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

-- End --

## Technical Service Bulletin

Jan 24, 2022

### RSP-1576MKII - Version 3.07 Software Release

The RSP-1576MKII software has been updated to includes bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V3.07
Previous Version	V3.06

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	258-136-1150
Silver	758-136-1050

Release Notes
<ul style="list-style-type: none"><li>● Implemented a warning message "The unit will automatically power off after the update is complete." at the end of upgrade.</li><li>● Enhanced software upgrade fault handling mechanism.</li><li>● Improved the consistency of internal generated test tone default level for manual room calibration as well as Dirac room calibration.</li><li>● Fixed a bug where unexpected erasure of Dirac profiles happened occasionally.</li><li>● Other minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

-- End --

## Technical Service Bulletin

October 22, 2021

### RSP-1576MKII – Version 3.06 Software Release

The RSP-1576MKII software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V3.06
Previous Version	V3.04

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	258-113-1150
Silver	758-113-1050

Release Notes
<ul style="list-style-type: none"><li>Supported new update MCU chipset.</li></ul>

*For more information or questions please contact your customer service representative.*

*-- End --*

## Technical Service Bulletin

July 19, 2021

### RSP-1576MKII – Version 3.04 Software Release

The RSP-1576MKII software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V3.04
Previous Version	V3.03

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	258-113-1150
Silver	758-113-1050

Release Notes
<ul style="list-style-type: none"><li>• Improved the consistency of internal generated test tone default level in subwoofer for manual room calibration.</li><li>• Optimized the output level in subwoofer when engaged Dolby Atmos Surround or DTS Neural:X remixing mode, and loaded Dirac filter.</li><li>• Enhanced the reliability and inter-operability performance of when click [&gt;] play button to generate test tone in Dirac Live app.</li><li>• Improved Dirac calibrating performance in speaker distance.</li><li>• Fixed an error where there was no generated test tone from Height 1 and Height 2 pre-outputs when configured as "HIGH FRONT" or "HIGH REAR" speakers under x.x.2 audio system.</li><li>• Fixed an inconsistency error, to remove "OVERHEAD / HIGH" speaker configuration option from main menu under 5.1 or 7.1 audio system.</li><li>• Fixed a hiccups / stutters error when switching the digital audio stream from Dolby Digital "5.1" to "2.0".</li><li>• Fixed a 12V trigger function error, to avoid system accidentally powering on a 12V trigger connected amplifier when the unit enters standby mode.</li></ul>

*For more information or questions please contact your customer service representative.*


-- End --

## Technical Service Bulletin

December 04, 2020

### RSP-1576MKII - Version 3.03 Software Release

The RSP-1576MKII software has been updated to include bug fixes and improvements as listed below.

Release Type		
 Maintenance	Major	Critical

Software Information	
New Version	V3.03
Previous Version	V3.01

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	258-030-1169
Silver	758-030-1030

Release Notes
<ul style="list-style-type: none"><li>• Fixed a bug where the unit had no output when processing Dolby Atmos content from Netflix.</li><li>• Implemented Dirac mode forced exit by pressing the BACK remote key.</li><li>• Updated the text of Online Upgrade process for better clarity.</li><li>• Fixed a bug where the unit failed to indicate Dolby 5.1 content from Netflix in the Display menu.</li><li>• Fixed a bug regarding Bass Management.</li><li>• Fixed remixing bugs that could led to audio stutter or no output in several occasions.</li><li>• Fixed a bug where abnormal output level occurred after going back to the Runtime screen from Speaker Level Menu with a Analog source and Stereo surround mode selected.</li><li>• Fixed Dirac bugs that were triggered by the change of Audio System Configuration.</li><li>• Minor bug fixes related to Dirac function.</li><li>• Minor bug fixes related to the Setup Menu operation.</li></ul>

*For more information or questions please contact your customer service representative.*

-- End --