# Technical Service Bulletin

March 20, 2024

## CD11MKII - Version 1.06 Software Release

The software has been updated to include bug fixes and improvements as listed below.

| Release Type | | |
|---|---|---|
| ☐ Maintenance | 🟥 Major | ☐ Critical |

| Software Information | |
|---|---|
| **New Version** | **V1.06** |
| Previous Version | V1.05 |

| Serial Number (Change will be effective in units start from the serial numbers listed below.) | |
|---|---|
| Black | 290-410-1001 |
| Sliver | 790-410-1001 |

| Release Notes |
|---|
| • Resolves random playback stopping with some discs. <br> • Minor bug fixes. |

*For more information or questions please contact your customer service representative.*

*- - End - -*

# Technical Service Bulletin

November 27, 2023

## CD11MKII - Version 1.05 Software Release

The software has been updated to include bug fixes and improvements as listed below.

| Release Type | | |
|---|---|---|
| ■ Maintenance | ☐ Major | ☐ Critical |

| Software Information | |
|---|---|
| **New Version** | **V1.05** |
| Previous Version | V1.04 |

| Serial Number (Change will be effective in units after the serial numbers listed below.) | |
|---|---|
| Black | 290-343-1100 |
| Sliver | 790-343-1100 |

| Release Notes |
|---|
| <br>● Fixed a bug where some discs caused the disc read error.<br>● Minor bug fixes.<br><br> |

*For more information or questions please contact your customer service representative.*

*- - End - -*

# Technical Service Bulletin

November 27, 2023

## CD11MKII - Version 1.04 Software Release

The software has been updated to include bug fixes and improvements as listed below.

| Release Type | | |
|---|---|---|
| ■ Maintenance | ☐ Major | ☐ Critical |

| Software Information | |
|---|---|
| **New Version** | **V1.04** |
| Previous Version | V1.02 |

| Serial Number (Change will be effective in units start from the serial numbers listed below.) | |
|---|---|
| Black | 290-343-1001 |
| Sliver | 790-343-1001 |

| Release Notes |
|---|
| ● Fixed a bug where the disc tray did not fully eject after the 12V-Trigger power on. <br> ● Optimized the brightness of the lowest Power LED brightness level. <br> ● Minor bug fixes. |

*For more information or questions please contact your customer service representative.*

*- - End - -*