ROTEL

Technical Service Bulletin

July 17, 2024

CD14MKII - Version 2.04 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
■ Maintenance	☐ Major	☐ Critical

Software Information	
New Version	**V2.04**
Previous Version	V2.03

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	274-423-1100
Sliver	774-423-1100

Release Notes
● Optimized Random mode strategy. ● Fixed a bug where the last track repeated forever after fast reversing the track for a few seconds. ● Minor bug fixes.

For more information or questions please contact your customer service representative.

- - End - -

Technical Service Bulletin

March 25, 2024

CD14MKII - Version 2.03 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
☐ Maintenance	🟥 Major	☐ Critical

Software Information	
New Version	**V2.03**
Previous Version	V2.02

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	274-402-1100
Sliver	774-402-1100

Release Notes
• Resolves random playback stopping with some discs. • Minor bug fixes.

For more information or questions please contact your customer service representative.

- - End - -

Technical Service Bulletin

November 27, 2023

CD14MKII - Version 2.02 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
🟥 Maintenance	☐ Major	☐ Critical

Software Information	
New Version	**V2.02**
Previous Version	V2.01

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	274-325-1200
Sliver	774-310-1100

Release Notes
• Optimized MCU communication scheme to eliminate unexpected playback stops. • Fixed a bug where the total remaining time in Program mode is incorrect. • Minor bug fixes and improvements.

For more information or questions please contact your customer service representative.

- - End - -

Technical Service Bulletin

July 10, 2023

CD14MKII - Version 2.01 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type				
🟥	Maintenance	☐ Major	☐	Critical

Software Information	
New Version	**V2.01**
Previous Version	V2.00

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	274-310-1100
Silver	774-310-1100

Release Notes
● Fixed a bug where sometimes unexpected playback stop occurred when the CD player played disc in REPEAT ALL mode.   ● Improved the PAUSE mode to automatically enter STOP mode after 5 minute to extend the life of CD mechanism.   ● Other minor bug fixes.

For more information or questions please contact your customer service representative.

- - End - -