

Technical Service Bulletin - Updated

Mar 28, 2019

CD14 - Version 1.31 Software Release

The CD14 software has been updated to Version 1.31. This release includes power consumption regulations. Release details are listed below.

Release Type					
Maintenance		Major		Critical	

Software Information				
New Version	V1.31			
Previous Version	V1.27			

Serial Number (Change will be effective in units starting with the serial numbers listed below.)			
Black	244-825-1001		
Silver	744-836-1001		

Release Notes

• Changed the default value of OFF TIMER from DISABLE to 20 MINS to meet the power consumption regulations.

Note that unit would enter STANDBY mode when the following conditions are fulfilled:

- a. Unit is in STOP state. (Pressing STOP key twice)
- b. No RS232 or ROTEL LINK communication
- c. No actions from remote control or front panel keys
- Added OFF TIMER warning message display. Unit will display a blinking remaining-time message three times in the last three minutes, each for 5 seconds, and will display a static warning message in the last ten second.

For more information or questions please contact your customer service representative.

- - End - -



Technical Information

DATE: October 25, 2016 MODEL: CD14

Software Release Notes

The following document contains details of the software updates for the CD14.

Key:

New Feature Feature Change Bug Fix - Critical Bug Fix - Minor

Main Software

V1.24 to V1.27 October 25, 2016

- Bug Fix (Minor): Fixed an issue where user set dimmer settings could be reset after a power cycle.
- Bug Fix (Minor): Fixed an intermittent bug where the display would show track names from the previous disc played when a new CD was first inserted.

V1.22 to V1.24

September 19, 2016

- Bug Fix (Minor): Fixed an intermittent bug where the display would remain displaying "EJECT" until the play button is pushed.
- Bug Fix (Minor): Improved error correction when playing scratched CDs.