

Technical Service Bulletin

July 21, 2023

A11Tribute - Version 1.21 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.21
Previous Version	V1.20

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	263-323-1001
Sliver	763-323-1001

Release Notes
<ul style="list-style-type: none">• Production testing improvements.

For more information or questions please contact your customer service representative.

-- End --

Technical Service Bulletin

July 21, 2023

A11Tribute - Version 1.20 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.20
Previous Version	V1.19

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	263-238-1001
Sliver	763-238-1001

Release Notes
<ul style="list-style-type: none"> Improved the ability to process ADC signal to fix a bug where sometimes the unit missed front panel source button requests.

For more information or questions please contact your customer service representative.

-- End --

Technical Service Bulletin

July 21, 2023

A11Tribute - Version 1.19 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.19
Previous Version	V1.17

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	263-230-1001
Sliver	763-230-1001

Release Notes
<ul style="list-style-type: none"> Supports high quality aptX™ HD Bluetooth wireless audio streaming in units starting with serial numbers listed above. Minor bug fixes.

For more information or questions please contact your customer service representative.

-- End --

Technical Service Bulletin

Nov 9, 2021

A11 Tribute– Version 1.17 Software Release

The A11 software has been updated to include bug fixes and improvements as listed below.

Release Type		
 Maintenance	Major	Critical

Software Information	
New Version	V1.17
Previous Version	V1.16

Serial Number (Change will be effective in units star from the serial numbers listed below.)	
Black	263-125-1001
Silver	763-125-1001

Release Notes
<ul style="list-style-type: none">• Further optimize user experience by eliminating the relay control action when there is a pause to the Bluetooth audio.

For more information or questions please contact your customer service representative.


-- End --

Technical Service Bulletin

Jan 28, 2021

A11 - Version 1.16 Software Release

The A11 software has been updated to includes bug fixes and improvements as listed below.

Release Type		
 Maintenance	Major	Critical

Software Information	
New Version	V1.16
Previous Version	V1.15

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	263-102-1200
Silver	763-102-1300

Release Notes
<ul style="list-style-type: none">• Updated for additional hardware support.

For more information or questions please contact your customer service representative.

-- End --



Technical Service Bulletin

Apr 25, 2019

A11 - Version 1.15 Software Release

The A11 software has been updated to Version 1.15. This release includes several bug fixes and improvements. Release details are listed below.

Release Type	
Maintenance	Major

Software Information	
New Version	V1.15
Previous Version	V1.14

Serial Number (Change will be effective in units starting from the serial numbers listed below.)	
Black	252-916-1001
Silver	752-916-1001

Release Notes
<ul style="list-style-type: none">Fixed a bug the unit unintentionally responded to IR commands from the CD remote.
<ul style="list-style-type: none">Improved the experience of setting FIX VOLUME allowing the volume level to change real-time when setting the fixed volume level in the setup menu.
<ul style="list-style-type: none">Fixed a bug with Tone Bypass to retain the current bypass mode setting after entering and exiting Setup Menu.
<ul style="list-style-type: none">Improved a bug where the Bluetooth lost memory and would not connect.

For more information or questions please contact your customer service representative.

-- End --