Technical Service Bulletin

November 1, 2023

T11 - Version 1.20 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information					
New Version	V1.20				
Previous Version	V1.19				

Serial Number (Change will be effective in units start from the serial numbers listed below.)					
Black	245-138-1001				
Sliver	745-145-1001				

Release Notes

- Implemented AC Power Option to allow the unit to remain in standby mode in the event of a power failure to avoid the unit powering on to operating mode after the AC power is restored.
- Minor bug fixes and improvements.

For more information or questions please contact your customer service representative.

- - End - -



Technical Service Bulletin

Dec 10, 2020

T11 - Version 1.19 Software Release

The T11 software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information					
New Version	V1.19				
Previous Version	V1.18				

Serial Number (Change will be effective in units start from the serial numbers listed below.)				
Black	245-042-1001			
Silver	745-042-1001			

Release Notes

- Added support for new FM/DAB module (V2).
- Other minor bug fixes.

For more information or questions please contact your customer service representative.

- - End - -



Technical Service Bulletin

July 10, 2019

T11 - Version 1.18 Software Release

The T11 software has been updated to Version 1.18. This release includes one improvement. Release details are listed below.

Release Type		
Maintenance	Major	Critical

Software Information					
New Version	V1.18				
Previous Version	V1.17				

Serial Number (Change will be effective in units after the serial numbers listed below.)					
Black 245-923-1100					
Silver	745-923-1100				

Release Notes

• Improved the reliability of the startup process of the unit.

For more information or questions please contact your customer service representative.

- - End - -



Technical Service Bulletin - Updated

Mar 28, 2019

T11 - Version 1.17 Software Release

The T11 software has been updated to Version 1.17. This release includes several bug fixes and improvements. Release details are listed below.

Release Type		
Maintenance	Major	Critical

Software Information				
New Version	V1.17			
Previous Version	V1.13			

Serial Number (Change will be effective in units starting with the serial numbers listed below.)					
Black	245-842-1001				
Silver	745-842-1001				

Release Notes

- Fixed a bug text overlap error would occur when pressed [FM MONO] button during radio station preset operation.
- Improved RDS scrolling text display to display real-time time and date information.
- Fixed a bug unit failed to wake up from standby mode when it received an source command that matched the last listening source.

Example:

Put unit into standby mode when the last listening source is FM, unit would failed to wake up when it received command "fm!".

• Fixed a bug unit would stuck at "Selecting..." display when it received command "dab!" during statup.

For more information or questions please contact your customer service representative.