

Technical Service Bulletin

September 7, 2022

Michi S5 - Version 1.05 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
 Maintenance	Major	Critical

Software Information	
New Version	V1.05
Previous Version	V1.04

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	254-228-1001

Release Notes
<ul style="list-style-type: none">• Implemented a Temperature Unit option to allow the user to change temperature unit between Celsius and Fahrenheit.• Fixed a bug where the system sent out incorrect power status feedback when in Quick standby mode.• Other minor bug fixes.

For more information or questions please contact your customer service representative.

-- End --


MICHI

Technical Service Bulletin

Dec 22, 2021

S5 - Version 1.04 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
 Maintenance	Major	Critical

Software Information	
New Version	V1.04
Previous Version	V1.03

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	254-147-1001

Release Notes
<ul style="list-style-type: none">• Fixed a display error where the left and right channels of VU meter is in reverse order.• Other minor bug fixes.

For more information or questions please contact your customer service representative.

-- End --

MICHI

Technical Service Bulletin

June 23, 2021

S5 - Version 1.03 Software Release

The Michi S5 software has been updated to Version 1.03. This release includes several improvements. Release details are listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.03
Previous Version	V1.02

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	254-120-1001

Release Notes
<ul style="list-style-type: none">• Fixed an occasional system halt and no power LED error when a push-hold on IR remote [POWER] button to go to standby mode is longer than ~3 seconds.• Other minor bug fixes and improvements.

For more information or questions please contact your customer service representative.

-- End --



Technical Service Bulletin

Sept 23, 2019

S5 - Version 1.02 Software Release

The Michi S5 software has been updated to Version 1.02. This release includes one improvement. Release details are listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.02
Previous Version	V1.00

Serial Number (Change will be effective in units starting with the serial numbers listed below.)	
Black	254-938-1001

Release Notes
<ul style="list-style-type: none">Updated the runtime screen to indicate the real-time temperature of both left and right amplifier modules.

For more information or questions please contact your customer service representative.

-- End --