

Technical Service Bulletin

July 27, 2023

Michi X3 Series2 - Version 2.01 Software Release

The software has been updated to include bug fixes and improvements as listed below.

| Release Type | | |
|--------------|-------|----------|
| Maintenance | Major | Critical |

| Software Information | | |
|----------------------|-------|--|
| New Version | V2.01 | |
| Previous Version | V2.00 | |

| Serial Number (Change will be effective in units after the serial numbers listed below.) | | |
|--|--------------|--|
| Black | 283-325-1050 | |

Release Notes

- Implemented Child Lock to allow the user to lock the front panel control to prevent changing the source input and volume level.
- Fixed a bug where the channels of VU meter were reversed. (contact sales@rotel.com if your unit appears affected by this issue for instructions)
- Fixed a bug where the VU meter has no movement.
- Fixed a bug where a high frequency noise occurred when the display brightness was change to "Medium" or "Medium High".
- Fixed a bug where the output channel was reversed when the user was playing DSD audio.
- Other minor bug fixes.

For more information or questions please contact your customer service representative.

- - End - -