


# MICHI

## Technical Service Bulletin

May 27, 2025

### Michi X5 Series2 - Version 2.05 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type			
 Maintenance		Major	Critical

Software Information	
New Version	V2.05
Previous Version	V2.03

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	284-508-1050

Release Notes
<ul style="list-style-type: none"><li>• Implemented a timeout function for the VU Meter and Spectrum display. When no audio signal is detected for 5 seconds, the unit will automatically return to the default runtime screen, allowing the user to view input source, volume level and other system information.</li><li>• Fixed a bug where the system failed to retain user-corrected reversed channel settings for the VU meter or Spectrum display after a reboot.</li><li>• Manufacturing testing improvements.</li><li>• Other minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

*- - End - -*


# MICHI

## Technical Service Bulletin

December 19, 2023

### Michi X5 Series2 - Version 2.03 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type			
 Maintenance		Major	Critical

Software Information	
New Version	V2.03
Previous Version	V2.02

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	284-343-1050

Release Notes
<ul style="list-style-type: none"><li>• Implemented Gain Adjust function to allow an independent level adjustment for sources.</li><li>• Implemented Child Lock to allow the user to lock the front panel to prevent changing the source input and volume level.</li><li>• Implemented "Max Volume" to limit the maximum volume to which the unit can turn.</li><li>• Improved the accuracy of the VU meter display with low volume.</li><li>• Other minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*


*- - End - -*

# Technical Service Bulletin

May 30, 2023

## MICHI-X5S2 - Version 2.02 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type			
 Maintenance		Major	Critical

Software Information	
New Version	V2.02
Previous Version	V2.00

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	284-312-1001

Release Notes
<ul style="list-style-type: none"><li>• Improved Network function to eliminate “No Network” problem during online software update.</li><li>• Fixed a bug where Home Theatre Trigger was not activated when the user turned on HT Bypass.</li><li>• Fixed a bug where the L and R channels of the spectrum were reversed.</li><li>• Fixed a bug where VU meter did not function properly at some conditions.</li><li>• Other minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

*- - End - -*