

## Technical Service Bulletin

June 16, 2022

### RC-1590MKII - Version 2.03 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V2.03
Previous Version	V2.02

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	270-208-1100
Silver	770-208-1100

Release Notes
<ul style="list-style-type: none"><li>Minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

*-- End --*

## Technical Service Bulletin

June 16, 2022

### RC-1590MKII - Version 2.02 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V2.02
Previous Version	V2.01

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	270-208-1001
Silver	770-208-1001

Release Notes
<ul style="list-style-type: none"><li>Implemented Home Theater Bypass to allow the front left and right speakers to be utilized for both music and movies.  Connect the Front Left and Front Right analog pre-outputs of a Home Theatre Receiver or Surround Sound Processor to the Rotel AUX or BAL-XLR source inputs and enable Home Theatre Bypass in the Rotel setup menu. When the Home Theater Bypass source is selected via the front panel or remote control on the Rotel product the analog audio will bypass the volume controller and route the audio directly to the amplification stage allowing audio from the Home Theater product to utilize the Rotel units amplifiers for the front channels.  A gain level adjustment setting —Home Theater Bypass Level — is also available in the SETUP menu after Home Theatre Bypass is enabled for precise gain control of the amplification stage.</li><li>Other minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

*-- End --*

## Technical Service Bulletin

June 16, 2022

### RC-1590MKII - Version 2.01 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V2.01
Previous Version	V2.00

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	270-208-1001
Silver	770-208-1001

Release Notes
<ul style="list-style-type: none"><li>Added AUTO option into Signal Sense to monitor all Signal Sense available sources. (this feature is not available in all markets) When Signal Sense is enabled and the current listening source is a Signal Sense available source, the unit will enter Signal Sense Standby mode after 10 minutes no audio signal detected. When Signal Sense = AUTO and an audio signal is detected on any Signal Sense available sources during Signal Sense Standby, the system will turn on the unit and switch to that source.</li><li>Implemented AC Power Option to allow the unit to remain in standby mode in the event of a power failure to avoid the unit powering on to operating mode after the AC power is restored.</li><li>Other minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

-- End --