

Technical Service Bulletin

December 21, 2022

C8/C8+ - Version 1.04 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information		
New Version	V1.04	
Previous Version	V1.03	

Serial Number (Change will be effective in units after the serial numbers listed below.)		
Black	277-238-1100	

Release Notes

- Improved temperature feedback method to improve accuracy.
- Fixed a bug where power LED occasionally flickers during booting up.
- Other minor bug fixes.

For more information or questions please contact your customer service representative.

- - End - -