

Technical Service Bulletin

Dec 10, 2020

T14 - Version 1.35 Software Release

The T14 software has been updated to include bug fixes and improvements as listed below.

Release Type		
 Maintenance	Major	Critical

Software Information	
New Version	V1.35
Previous Version	V1.33

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	246-042-1001
Silver	746-042-1001

Release Notes
<ul style="list-style-type: none">• Added support for new FM/DAB module (V2).• Fixed a bug where white screen occurred occasionally during Play-Fi playback.• Fixed a bug where the POWER LED did not indicate in red in Standby mode in units with the new FM/DAB module.• Other minor bug fixes.

For more information or questions please contact your customer service representative.

-- End --



Technical Service Bulletin

July 10, 2019

T14 - Version 1.33 Software Release

The T14 software has been updated to Version 1.33. This release includes one bug fix and one improvement. Release details are listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.33
Previous Version	V1.31

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	246-821-1100
Silver	746-821-1100

Release Notes
<ul style="list-style-type: none">• Fixed a bug Play-Fi Preset is broken after Play-Fi firmware upgrade.• Improved the reliability of the startup process of the unit.

For more information or questions please contact your customer service representative.

-- End --



Technical Information

DATE: January 18, 2018 **MODEL:** T14

Software Release Notes

The following document contains details of the software updates for the T14.

Key:

New Feature

Feature Change

Bug Fix – Critical

Bug Fix – Minor

V1.29 to V1.31

January 18, 2018

- **New Feature:** Enabled to save the DTS Play-Fi streaming stations in a preset.
- **Bug Fix (Minor):** Fixed a bug on display when paused and skipped Spotify music playback to next track.

V1.25 to V1.29

November 8, 2016

- **Bug Fix (Minor):** Fixed a bug where the front display could display overlapping text if the FM MONO button is pushed while the preset memory dialog box is active.
- **Bug Fix (Minor):** Minor updates to the DTS Play-Fi module to improve interoperability and user experience when used with the Play-Fi iOS app.