

# Technical Service Bulletin

December 4, 2024

## CD11MKII - Version 1.09 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.09
Previous Version	V1.08

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	290-438-1001
Sliver	790-443-1001

Release Notes
<ul style="list-style-type: none"><li>Fixed a bug where a disc loading error could occur on a few units when reading some specific discs. (Note: A hardware modification may be required if the above software does not fully resolve isolated disc reading errors.)</li><li>Minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

-- End --

# Technical Service Bulletin

September 9, 2024

## CD11MKII - Version 1.08 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
<b>New Version</b>	<b>V1.08</b>
Previous Version	V1.07

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	790-435-1001
Sliver	290-435-1001

Release Notes
<ul style="list-style-type: none"> <li>• Resolves random playback stopping with some discs.</li> <li>• Fixed a bug where sometimes noise could be heard when switching back to the 1st track.</li> <li>• Minor bug fixes.</li> </ul>

*For more information or questions please contact your customer service representative.*

*-- End --*

# Technical Service Bulletin

July 17, 2024

## CDIIMKII - Version 1.07 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.07
Previous Version	V1.06

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	290-421-1200
Sliver	790-414-1100

Release Notes
<ul style="list-style-type: none"><li>• Optimized Random mode strategy.</li><li>• Fixed a bug where the last track repeated forever after fast reversing the track for a few seconds.</li><li>• Minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*


-- End --

# Technical Service Bulletin

March 20, 2024

## CDIIMKII - Version 1.06 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type			
Maintenance		Major	Critical

Software Information	
New Version	<b>V1.06</b>
Previous Version	V1.05

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	290-410-1001
Sliver	790-410-1001

Release Notes
<ul style="list-style-type: none"><li>● Resolves random playback stopping with some discs.</li><li>● Minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

-- End --

# Technical Service Bulletin

November 27, 2023

## CDIIMKII - Version 1.05 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
<b>New Version</b>	<b>V1.05</b>
Previous Version	V1.04

Serial Number (Change will be effective in units after the serial numbers listed below.)	
Black	290-343-1100
Sliver	790-343-1100

Release Notes
<ul style="list-style-type: none"> <li>• Fixed a bug where some discs caused the disc read error.</li> <li>• Minor bug fixes.</li> </ul>

*For more information or questions please contact your customer service representative.*

-- End --

# Technical Service Bulletin

November 27, 2023

## CDIIMKII - Version 1.04 Software Release

The software has been updated to include bug fixes and improvements as listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	<b>V1.04</b>
Previous Version	V1.02

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	290-343-1001
Sliver	790-343-1001

Release Notes
<ul style="list-style-type: none"><li>• Fixed a bug where the disc tray did not fully eject after the 12V-Trigger power on.</li><li>• Optimized the brightness of the lowest Power LED brightness level.</li><li>• Minor bug fixes.</li></ul>

*For more information or questions please contact your customer service representative.*

-- End --