

MICHI

Technical Service Bulletin

June 23, 2021

M8 - Version 1.03 Software Release

The Michi M8 software has been updated to Version 1.03. This release includes several improvements. Release details are listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.03
Previous Version	V1.02

Serial Number (Change will be effective in units start from the serial numbers listed below.)	
Black	256-121-1001

Release Notes
<ul style="list-style-type: none">• Fixed an occasional system halt and no power LED error when a push-hold on IR remote [POWER] button to go to standby mode is longer than ~3 seconds.• Other minor bug fixes and improvements.

For more information or questions please contact your customer service representative.

-- End --



Technical Service Bulletin

Sept 23, 2019

M8 - Version 1.02 Software Release

The Michi M8 software has been updated to Version 1.02. This release includes one improvement. Release details are listed below.

Release Type		
Maintenance	Major	Critical

Software Information	
New Version	V1.02
Previous Version	V1.00

Serial Number (Change will be effective in units starting with the serial numbers listed below.)	
Black	256-939-1001

Release Notes
<ul style="list-style-type: none">Updated the runtime screen to indicate the real-time temperature of both left and right amplifier modules.

For more information or questions please contact your customer service representative.

-- End --